





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD...




- 1 = A 962 361 LJ
- 3 = A 962 232 XX
- 4 = A 962 998 NU (2x)
- 5 = A 962 233 XX
- 6 = A 963 427 NU
- 7 = F 961 044 NU
- 8 = A 962 230 NU
- 10 = A 963 432 NU
- 11 = A 963 400 NU
- 16 = A 962 594 NU (2x) (A5677)
= F 960 942 NU (1x) (A5832)
- 17 = A 961 810 NU (2x)
- 19 = A 962 595 NU (2X)
- 20 = A 960 914 XX
- 21 = A 960 975 XX (2x)





CERATHERM 50

A5677.. A5832.. A6367.. A6370..
A4506.. A6368.. A6369..

1014 / A 866 891
(+ A 865 612)
Made in Germany






A4506..



Ideal Standard International BVBA
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com





	P	bar		MAX. 10		5			Q (3 bar)
	T	°C		MAX. 80		65			l/min
						55			20,5

